

Images of Earthquake Effects

1994 Northridge, CA Earthquake (M 6.7)



Damage from the 1994 Northridge earthquake, CA (M 6.7)

Damage from the 1994 Northridge earthquake, CA (M 6.7)





Damage to freeway columns from the 1994 Northridge, CA earthquake (M 6.7)

1995 Kobe, Japan Earthquake (M 6.9)



1995 Kobe, Japan earthquake (M 6.9) – damage from ground shaking



1995 Kobe, Japan earthquake (M 6.9) – damage from ground shaking



1995 Kobe, Japan earthquake (M 6.9) – damage from ground shaking



1995 Kobe, Japan earthquake (M 6.9) – damage from ground shaking



1995 Kobe, Japan earthquake (M 6.9) – damage from ground shaking



1995 Kobe, Japan earthquake (M 6.9) – damage from ground shaking



1995 Kobe, Japan earthquake (M 6.9) – damage from ground shaking

Other Earthquakes



Collapsed buildings from the 1999 Izmit, Turkey earthquake

Collapsed building from
the 1999 Taiwan
earthquake (M 7.6)





Collapsed building from 2001 Gujarat, India earthquake (M 7.7)




Collapsed building from 2001 Gujarat, India earthquake (M 7.7)



Damage in Seattle, WA from a 2001 earthquake

Fence deformed by Love surface waves during the 1959 Gallatin County, MT earthquake





Tracks deformed by Love surface waves during a 1977 earthquake in Guatemala